

## Appendix B - Condition Report Photos




Figure 1 - IMG\_2858.jpg




Figure 2 - IMG\_2859.jpg



Figure 3 - IMG\_3860.jpg



Figure 4 - IMG\_2861.jpg



Figure 5 - IMG\_3865.jpg



Figure 6 - IMG\_3866.jpg



Figure 7 - IMG\_3867.jpg showing cracking of wood.



Figure 8 - IMG\_3868.jpg



Figure 9 - IMG\_3868.jpg



Figure 10 - IMG\_3869.jpg NB: Part numbers on boiler.



Figure 11 - IMG\_3870.jpg NB: Waterous Logo Nameplate



Figure 12 - IMG\_3871.jpg




Figure 13 - IMG\_3872.jpg



Figure 14 - IMG\_3873 NB: Rock next to sign at the top of the photo was thrown at the glass enclosure in June 2015. No damage appears to have occurred to the artifacts.